

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O Ms. 20/70/PWD dt.23.01.1970)

1 Name of the Officer

Elizabeth C X

2 Name of the School

Santa Cruz Public School

3 Location with name of Education District
/Sub District

Eramalloor, Cherthala

Classification of Building as specified in
column 4 of the application for fitness
certificate and size

RCC Multistoried Building

GF	FF	SF
Class Room-9 nos 6.8 x 6 x 3.60m	ClassRoom- 10 nos 6.80 x 6 x 3.60m	Science Lab- 1no 24.3 x 6 x 3.6m
Class Room- HSS- 2nos 10.3 x 6.00 x 3.6m	ClassRoom HSS- 4 nos 10.3 x 6 x 3.60m	Chemistry Lab- 1no 13.8 x 6 x 3.6m
Office- 1no 6.8 x 6 x 3.6 m	Computer Room-1no 6.8 x 6 x 3.6m	Physics Lab-1no 17.2 x 6 x 3.6m
Staff Room- 1no 13.3 x 6 x 3.60m	Prayer Room-1no 13.3 x 6 x 3.6m	Maths Lab- 1no 10.3 x 6 x 3.6m
Lobby - 1no 6.6 x 6 x 3.6m	Library & Reading Room- 1no 10.30 x 6 x 3.60m	Audio Visual Room- 1no 20.8 x 6 x 3.6m
Manager Room- 1no 6.6 x 6 x 3.6m	Store Room- 3.30 x 6m	Art Edn Room- 1no 10.3 x 6 x 3.6m
Principal Room - 1no 5.00 x 6 x 3.6m	Stair Room- 2.8 x 6 m	Class Room HSS- 2nos 10.3 x 6 x 3.6m
Junior Principal Room - 1no 5 x 6 x 3.6m	Toilet Block	Store Room- 5nos 3.3 x 6 x 3.6m
Stair Room-3nos 2.80 x 6.0m	Girls 1no 11' x 20'	Stair Room-3nos 2.8 x 6 m
Sick Room- 1no 6.6 x 6m	Boys -1no 11' x 20'	Toilet Block
Store Room - 1no 3.3 x 6m		Girls - 1no 11' x 20'
Toilet Block		Boys 1 no 11' x 20'
Girls- 1no 11' x 20'		
Boys -1no 11' X 20'		

Period for which the certificate is issued

2025-2026

Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and windows
- d) Wood work wrought and

NIL

NIL

NIL

NIL

- | | | |
|----|---|---|
| e) | Roof | NIL |
| f) | Flooring | NIL |
| g) | Miscellaneous (cracks etc) | NIL |
| 7 | Any major defects noticed which will render the building unsafe in any manner | No |
| 8 | Whether maintenance works have been done properly | Yes |
| 9 | Whether the structure is sound or not for conducting classes | The structure is sound for conducting classes under normal kerala weathering conditions |

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the school building was inspected by me on **23.05.2025** and found to be fit to conduct classes under normal weather conditions, for the period **01.06.2025 to 31.03.2026** for the reasons stated above.

Place: Eramalloor
Date: 23.05.2025



E. L. S. Th
Assistant Engineer
LIN & EW Section
Fzhubunna Grama Pa Ichavai

M. Diana
MARY DIANA

Antony Santhosh Xarkie
Self attested